Quick User Guide

Operation:

1. Press [⏻] to turn the scale on.
2. Wait for the display to show zero before weighing.
3. Place the items to be weighed on the center of the platform.
4. You can change the unit of measure by pressing the [UNIT] key.

Tare Function:

1. Press the [TARE] key to re-ze[illegible]he scale. Using the tare func[illegible]n, you can subtra[illegible]he weight of a containe[illegible]o obtain the weig[illegible]f just the contents.

Calibration Adjustment:

If the scale is weighing inaccurately, it may be time to perform a calibration adjustment.

1. With the scale ON,press and hold the [UNIT] key until the display shows CAL then release.
2. Press the [UNIT] key once more. The display will flash CAL followed by"500.0g".
3. Place a 500 gram calibration weight on the center of the platform.
4. The display will flash"PASS"followed by"500.0g". Calibration is complete.

TARE
UNIT
PCS
Capacity : 500gX0.01g
0.00

Ardshinbank
00306557

Ոսկյա իրերի գրավի ստուգման և հանձնման-ընդ

N ԳՊ 2382661-079

6866671079

Ունիկալ համար

0 068666 710794

ԴԱՒԼԱՔՅԱՆ
ՍԵՐԳԵՅ
ՍՊԱՐՏԱԿԻ
G79062300119
Կնիքի համար՝
21740819
22/06/23

1.Վարկի
ժամկետ(օր) 185